Compatible Products for Nuclias Unity Solution

nuclias unity

Core Switches	HW Ver.	Supported FW
• DXS-3410-32XY/32SY[1,2]	Ax	v1.00.023 or latest
• DXS-3610-54S/54T[1,2]	Ax	v1.01.023 or latest
• DGS-3630-28PC/28SC/28TC/52TC/52PC[1,2]	Ax	v2.30.015 or latest
Aggregation Switches	**HW Ver.**	**Supported FW**
• DXS-3130-28/28P/32S[1]	Ax	*v1.31.001 or latest
• DMS-3130-30TS/30PS[1]	Ax	*v1.31.001 or latest
• DGS-3130-30S/30PS/30TS/54PS/54S/54TS[1]	Bx	*v2.04.001 or latest
Stackable Smart Switches	**HW Ver.**	**Supported FW**
• DGS-1510-20/28X/28XMP/28/28P/52/52X /52XMP[1,2]	Ax	Coming Soon
• DGS-1520-28/28MP/52/52MP[1,2]	Ax	v1.01.004 or latest
• DGS-1530-10/20/28/28P/52/52P/28S/28SC[1,2]	Ax	Coming Soon
Standard Smart Switches	**HW Ver.**	**Supported FW**
• DXS-1210-10TS/10MP/12SC/12TC/16TC	Bx	v2.11.002 or latest
• DXS-1250-12/12P/12S/28/28P/28S	Bx	Coming Soon
• DXS-1250-28YP[1]	Ax	v1.01.001 or latest
• DMS-1250-10S/10SP/10SPL/12/12TP/18/18P/28/28P	Ax	v1.03.014 or latest
• DGS-1210-10/10MP/10P/20/26/28/28MP/28P/52/52MP	Fx	*v6.33.004 or latest
• DGS-1250-28X/28XMP/52X/52XMP[2]	Ax	v2.10.005 or latest
• DGS-1250-28X/28XP/52X/52XP	Bx	v1.00.010 or latest
Easy Smart Switches	**HW Ver.**	**Supported FW**
• DXS-1100-10/10P/10TP	Bx	Coming Soon
• DGS-1100-16V2/18PV2/24PV2/24V2/26MPV2	Ax	v4.00.033 or latest
Access Point	**HW Ver.**	**Supported FW**
Wi-Fi 7		
• DAP-E9560	Ax	v1.01r028 or latest
• DAP-E3620OU	Ax	Coming Soon
• DAP-E3620W	Ax	Coming Soon
• DAP-E3620	Ax	v1.00r004 or latest
Wi-Fi 6		
• DAP-X3060OU	Ax	v1.10r016 or latest
• DAP-X3060W	Ax	v1.10r012 or latest
• DAP-X3060	Ax	v1.10r025 or latest
• DAP-X2810	Ax	v1.30r078 or latest

Business Router	HW Ver.	Supported FW
• DBR-700[1]	A1	v1.00.09 or latest
	A2	v1.00.09 or latest
• DBR-600-P[1]	A1	v1.00.06 or latest
	A2	v1.00.06 or latest

Note:
1. **Remote Access**: Supports remote access for device management.
2. **Unity Proxy Requirement**: Unity Proxy installation is required in order to manage devices via the Nuclias Unity Portal.
3. **Important Upgrade Notes(Two-Stage Upgrade)**: If your device is running a version lower than those listed below, a two-stage upgrade is required (install the interim version before updating to the target firmware):
*DXS-3130 AX & DMS-3130 AX Series: If lower than v1.30.000, update to v1.30.000 first.
*DGS-3130 BX Series: If lower than v2.04.000, update to v2.04.000 first.
*DGS-1210 FX Series: If lower than v6.30.16, update to v6.30.16 first.